







AWRI

Brine Temperatures

Process / Activity	Brine Set-Point	Refrigeration COP
Must Chilling / Juice Chilling	-3 °C	2.1
Fermentation	+2 °C	2.4
Cold Stabilisation	-7 °C	1.8
Wine Storage (winter)	+2 °C	2.5
Bottling	-3 °C	2.1



